

Fairbank Oakwood Construction Progress Update

Fairbank Station - Oakwood Station

November 3, 2021

METROLINX LAND ACKNOWLEDGMENT

Metrolinx acknowledges that it operates on the traditional territory of Indigenous Peoples including the Anishnabeg, the Haudenosaunee and the Wendat peoples.

In particular these lands are covered by 20 Treaties, and we have a responsibility to recognize and value the rights of Indigenous Nations and Peoples and conduct business in a manner that is built on the foundation of trust, respect and collaboration.

Metrolinx is committed to building meaningful relationships with Indigenous Peoples, and to working towards meaningful reconciliation with the original caretakers of this land.


Fairbank Station

FAIRBANK STATION UPDATES

| Activity | Location | Approx. Date & Duration |
|--|------------------------------------|-------------------------|
| Elevator 1 & Escalator Installations | Station Box | Completed October |
| Floor Tile Installation | Platform Level - West Side | Completed October |
| Granite Installation over Stairs | Station Box | Completed October |
| Tarping | Main Entrance | Completed October |
| Roof Installation | Secondary Entrance | Completed October |
| Sidewalk Restoration | South side of Eglinton Avenue West | Completed October |
| Wall & ceiling panel and tiling installations, light installations, exterior concrete framework, and surface works | Main Entrance | Ongoing through 2021 |
| Wall & ceiling panel and tiling installations, light installations | Secondary Entrance | Ongoing through 2021 |
| Electrical, mechanical, and architectural installation Elevator, escalator, and stairs. Tiling and finishes. | Station Box | Ongoing through 2021 |
| TVS Fan Installation | Service Building | Ongoing through 2021 |
| Sidewalk Restoration | Along Eglinton Avenue West | Ongoing through 2021 |


CURRENT TRAFFIC CONFIGURATION

October 28 - November 18, 2021




TRAFFIC CONFIGURATION

Through 2021



CONSTRUCTION PROGRESS PHOTOS



SIDEWALK RESTORATION COMPLETED ON THE SOUTH SIDE OF EGLINTON AVENUE WEST



ELEVATOR INSTALLATION IN PROGRESS AT THE MAIN ENTRANCE

CONSTRUCTION PROGRESS PHOTOS

TARPING COMPLETED AT THE MAIN ENTRANCE



TILE INSTALLATION IS COMPLETED ON WEST PLATFORM IN THE STATION BOX


Oakwood Station

OAKWOOD STATION UPDATE

| Activity | Location | Approx. Date & Duration |
|--|---|---------------------------|
| Station Box Construction Sign band installation, architectural finishes, and mechanical electrical works | Beneath Eglinton Avenue West between Times Rd and Oakwood Ave | Underway through 2021. |
| Main Entrance Construction Architectural works, escalator and stair installations | North side of Eglinton Avenue at Oakwood Avenue with material staging on Times Road <ul style="list-style-type: none"> • Periodic laneway closure behind Main Entrance for architectural works | Underway through 2021 |
| Secondary Entrance Construction Architectural works and final utility connections | Southside of Eglinton Avenue, west of Oakwood Avenue | Underway into Winter 2021 |


CURRENT TRAFFIC CONFIGURATION

Through 2021



TRAFFIC CONFIGURATION: LANEWAY CLOSURE

Periodically through 2021



CONSTRUCTION PROGRESS PHOTOS



